IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SRL-F
Release Version	3.74.10
Release Date	11/15/2019
Previous Version	3.73
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	 Added support for third number (build version) of IPMI firmware version. Added BMC Account Security. Added modification for event severity. Enabled sending all event logs (Health & Maintenance) to Syslog server. Added UefiPxe to Redfish System boot order. Added BMC firmware solution to program and store unique preprogrammed password.
Fixes	1. Fixed incorrect KEYPAD * and + key maps via IPMI iKVM console and KEYPAD on physical keyboard.

- 2. Fixed failure to preserve the BMC configuration from release version to new version.
- 3. Fixed problem of IPMI WebGUI system status showing as critical after CPU overheat de-assertion.
- 4. Fixed problem of SEL showing error message after AOC-S3108 updates firmware.
- 5. Fixed multiple vulnerabilities with Supermicro BMC Virtual Media.
- 6. Corrected maximum allowed password length shown for /redfish/v1/AccountService MaxPasswordLength.
- 7. Fixed issue with IPMI web formatting for system.
- 8. Fixed failure of SATC Redfish automation test and inability to access Redfish with RADIUS session after factory default.
- 9. Fixed problem of IPMI RADIUS authentication client returning Localhost IP In NAS-IP-Address/, malfunction of IPMI RADIUS authentication if authentication is delayed for over 3 seconds, and problem of IPMI RADIUS authentication violating attribute 26 specification.
- 10. Fixed missing leading zero in minor version of /Managers/1/ FirmwareVersion.
- 11. Corrected verification of the concatenate string of unique password.
- 12. Fixed failure of Java KVM to block Virtual Media section and show warning message when virtual media port is disabled.