

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X10DRU-XLL</b>
<b>Release Version</b>	<b>3.2 SPS: 3.1.3.72</b>
<b>Release Date</b>	<b>12/2/2019</b>
<b>Build Date</b>	<b>12/2/2019</b>
<b>Previous Version</b>	<b>3.1c</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>1. Updated SINIT ACM 3.1.4 PW for Intel-SA00240 (CVE-2019-0151 CVSS 3.1: 7.5 High). 2. Updated SATA/sSATA RAID OPROM/EFI driver to VROC PreOS v6.2.0.1034. 3. Updated Broadwell-EP B0/M0/R0 CPU microcode MEF406F1_0B000038 for Intel-SA00219 (CVE-2019-0117) and Intel-SA00220 (CVE-2019-0123).</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>N/A</b>

*Release Notes from Previous Release(s)*

**3.1c (6/28/2019)**

1. *Changed BIOS revision to 3.1c.*
2. *Updated Post Launch Release 072 for Grantley Server for INTEL-SA-00213 Security Advisory to address CVE-2019-0089, CVE-2019-0090, CVE-2019-0086, CVE-2019-0091, CVE-2019-0092, CVE-2019-0093, CVE-2019-0094, CVE-2019-0096, CVE-2019-0097, CVE-2019-0098, and CVE-2019-0099 security issues.*
3. *Updated SATA/sSATA RAID OPROM/EFI driver to VROC PreOS v6.1.0.1017.*
4. *Updated Haswell-EP/Broadwell-EP CPU microcode from SRV\_P\_273 for INTEL-SA-00233 Security Advisory to address CVE-2018-12126, CVE-2018-12127, and CVE-2018-12130 security issues.*
5. *Added support for RFC4122 UUID format feature to set RFC4122 encoding from build time produced by IPMICFG 1.29 tool or newer.*
6. *Updated VBIOS and VGA EFI Driver to 1.09.*
7. *Updated CPU microcode for PC6 issue.*
8. *Updated Broadwell-EP RC 4.4.0 release.*

**3.1 (6/12/2018)**

1. *Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue.*
2. *Updated Broadwell-EP RC 4.4.0 release.*
3. *Fixed issue of system hanging while doing the ONOFF test with AOC-3108.*

**3.0a (2/22/2018)**

1. *Implemented enhancement to address 'Spectre' variant 2 (CVE 2017-5715) security patch issue.*
2. *Updated Broadwell-EP RC 4.3.0 PLR11 release.*
3. *Updated Intel Server Platform Services 3.1.3.38 PLR7 for Grantley Refresh Platforms.*
4. *Fixed issue of kernel panic occurring with Redhat 7.3 (Kernel 3.10.0.514) when limiting cores.*