

IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRU-XLL
Release Version	3.86
Build Date	11/15/2019
Previous Version	3.84
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Merged X11 SMASH overflow and rearrange method.
New features	1. Added BMC firmware solution to program and store unique pre-programmed password.
Fixes	1. Corrected problem hostname containing timestamp after updating IPMI firmware. 2. Corrected inability to update SMC3108 firmware from IPMI. 3. Allow modifying username with space. 4. Corrected iKVM display of "Virtual Media". 5. Corrected inability to launch SOL window. 6. Corrected message that is displayed when iKVM port is unchecked.