## **IPMI Firmware Release Notes**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	B2SD1/B2SD2-TF series
Release Version	5.72.05
<b>Build Date</b>	4/7/2020
<b>Previous Version</b>	5.72.01
<b>Update Category</b>	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Updated Jarsigner certificate and set to use OpenJDK8 instead of Oracle.
	2. Fixed malfunction of WebGUI display when hostname is too long.
	3. Fixed failure to install OS when mounting large ISO image (over than 5GB)
	through HTTP.
	4. Enabled CMM to detect the VM port status of BMC.
New features	None
Fixes	1. Fixed inability to save DDNS settings on web pages in Japanese/SC
	languages.
	2. Fixed inability of CMM to switch to HTML5.
	3. Fixed malfunction of UID Control page via Edge browser.
	4. Fixed problem of B11 BMC FW 5.72.00 failed on internal VLAN
	communication with CMM.