

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12DSU-iN
Release Version	3.10.05
Release Date	7/2/2020
Previous Version	3.10.03
Update Category	Recommended
Dependencies	BIOS v1.0a
Important Notes	IPMI Image: SMT_H12AST2500_64M_31005_V.bin IPMI Update Package: SMT_H12AST2500_64M_31005_V.ZIP
Enhancements	N/A
New features	N/A
Fixes	<ol style="list-style-type: none">1. Removed ability of all fans to run at 40% under idle mode.2. Fixed problem of NIC_TEMP1 sensor reading showing N/A at BMC 3.10.01.3. Fixed missing NVMe control under Server Health on IPMI WebGUI.4. Fixed missing NVIDIA T4 GPU card's information on IPMI Web UI.5. Fixed abnormality of TAS event severity on the IPMI Web/Health event on the H12DSU-iN.6. Fixed inability of the system to perform the Insert function when the Eject function is executed and no NVMe is found in storage monitoring.7. Fixed issues with NVMe hot-swap.8. Fixed bug with FRU chassis type.9. Removed MB_NIC_Temp 1 and 2.

Release Notes from Previous Release(s)

3.10.03 (6/2/2020)

Initial Release