

IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SCW-F
Release Version	3.76.24
Build Date	11/9/2020
Previous Version	3.76.20
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Added "Redfish Managers.Network Protocol" SSDP catalog. 2. Set SSDP to disabled by default.
New features	1. Added support for HTML5 VM. 2. Added support for IPv6/FQDN for LDAP/Radius/AD/Alert/VirtualMedia/SMTP/syslog/NTP/DDNS server.
Fixes	1. Fixed problem of Redfish returning 500 on RAID mode when getting Disk.Bay. 2. Fixed inability of OEM BIOS to execute OOB update and problem of 'Invalid Signature' appearing. 3. Fixed some account service items. 4. Fixed missing chassis intrusion sensor after 8 hours of cburn. 5. Fixed problem of NVMe and RAIDIntrate status always showing as warning.

	<p>6. Fixed inability of Redfish to get permission via AD user while enabling AD via SSL setting.</p> <p>7. Fixed failure of SATC Redfish API test case for BIOS upload.</p> <p>8. Fixed problems of chassis intrusion reading showing as N/A and power down failing during cburn DC cycle stress.</p> <p>9. Fixed problem of all sensor readings displaying as N/A when the AOC-S40G-i2Q card is inserted.</p> <p>10. Fixed failure of SUM test.</p> <p>11. Fixed problem of "Event Log" field on SEL GUI screen overlapping with "Keyword Search" field on Health Event Log page.</p> <p>12. Fixed mismatch of '30 6a SUM' and 'ipmitool' on DCMS/OOB license of X11DGQ-P.</p>
--	---

Release Notes from Previous Release(s)

3.76.20 (7/16/2020)

1. Blocked invalid input for Configuration Web.
2. Improved Visa security sensitive parameters.
3. Removed limitation to prevent IPv6 static router prefix length input of 0.
4. Added CSRF prevention feature.
5. Fixed inability to apply HTTP/HTTPS port number after restoring IPMI.
6. Removed sensitive parameters on main menu pages, specifically Remote Console Preview.
7. Fixed issue with Visa security for maintenance web pages.
8. Fixed issue with alert and AD web page.
9. Fixed problem of user being modified if given invalid input and problems when deleting an active directory.
10. Fixed problem of AOC NIC Temp sensor reading showing as n/a.
11. Fixed failure to update BIOS/BMC through SMCIPMITool/SUM.
12. Fixed Stunnel port response.
13. Fixed failure to use SUM tool to update BMC firmware.
14. Added CSRF token check mechanism into firmware upload CGI firmware_upload.cgi and fixed failure of syslog config setting due to HTTP server malfunction after disabling HTTP.
15. Fixed problem of unknown() appearing under the System Information/View Details on the X11SCW-F while H12DST-B and X11DPG-QT pass.
16. Fixed problem of EC update page returning error 403.
17. Fixed failure of Get Managers iKVM URI And Check when running Redfish Automation Tool.
18. Fixed inability to save SSDP setting.
19. Fixed problem of IPMI execution exception occurring when running IPMI Automation.

3.76.16 (5/6/2020)

1. Fixed inability to run HTML5 after 3.76.01 update from 3.68 for X11.

3.76.11 (3/26/2020)

1. Synced severity and description of SW team SELs.
2. Fixed failure to install OS when mounting large ISO image (over than 5GB) through HTTP.
3. Added support for new sensor health status.
4. Corrected status of share LAN shown by IPMI.
5. Fixed inability to save DDNS settings on web pages in Japanese/SC languages.
6. Fixed occurrence of DCMI power reading 0.
7. Corrected health event log severity and description.
8. Fixed inability to launch KVM console under IPMIView_2.17.0_build.191212.
9. Fixed problem of "PDSlot not present" BMC SEL occurring unexpectedly.

3.76.09 (2/12/2020)

1. Set copyright to 2020.
2. Improved the dump speed of system troubleshooting.
3. Updated Jarsigner certificate.
4. Added support for Java KVM text copy and paste feature.
5. Set BMC to store factory default option in flash.
6. Fixed problem of SNMP losing some sensor information.
7. Fixed failure to update BIOS built in 2020.

8. Fixed failure to restore https port when restoring IPMI configuration.
9. Fixed mismatch of IPMI WebUI Fan Mode Help description.
10. Fixed inability to add IPv6 address.
11. Fixed absence of event if NTP is enabled and NTP server is not accessed.
12. Set System troubleshooting to support download of Version.txt, Health event log, Maintenance event log, FRU, and SMBIOS information.
13. Fixed problem with CD-ROM image ISO mount with SUM.
14. Fixed issues with CD-ROM image and support for special characters in config username.
15. Fixed failure to release iKVM resource.
16. Fixed inability of some nodes to detect BMC IP Gateway at SYS-F619P2-FT-DTP1-TS29T (MBD: X11DPFF-SN).
17. Fixed inability of existing user to modify username on web page.
18. Fixed malfunction of WebGUI display when hostname is too long.

3.76.01 (10/30/2019)

1. Blocked iKVM virtual storage if VM port is disabled.
2. Updated system troubleshooting script to read PCH Register Data.
3. Provided more information for Processor Configuration Error.
4. Set IERR event and troubleshooting to enabled by default.
5. Modified boot option to adhere to Redfish description.
6. Fine tuned the VPP sensor threshold.
7. Added support for Redfish SecureBoot feature.
8. Added account lockout feature to temporary disable user if condition is met.
9. Defined common format to add Health and Maintenance events to syslog server.
10. Added display of all IPv4/IPv6 addresses on the sys_info page.
11. Added IPv6 Static Router.
12. Added support for Redfish simple update action.
13. Set IPv6 to disabled by default.
14. Added KCM privileges.
15. Added support for unique pre-programmed default password, form 299-00-190617-001.
16. Fixed failure to update BIOS by Redfish simple update action.
17. Set VM port 623 to close after disabling VM service.
18. Added VM Security patch.
19. Fixed enable/disable for Launch KVM button.
20. Fixed problem of BMC continuously rebooting if the dedicated LAN disconnects while dedicated mode is selected.
21. Fixed failure to mount CD-ROM image.
22. Fixed problem of setting ServiceEnable of IPAccessControl via Redfish returning HTTP status code 302.
23. Corrected reading of Peripheral Temperature as 127 degrees and added Inlet Temperature sensor.
24. Fixed failure of BMC to support clearing the recv irq bit, compensating.
25. Fixed Web session timing out when logging into BMC with AD/BMC account.
26. Fixed failure of IPMI to create a new event when attempting to log in using incorrect credentials.
27. Fixed issue with display of long AD domain name.
28. Fixed failure to change TPM state by IPMI raw command.
29. Fixed failure of SMSTC test with SMCIPMITool.
30. Fixed problem of too many IERR event logs generating when IERR is triggered.
31. Fixed failure of Redfish with 03.75.01.
32. Fixed failure of SUM test with IPMI 3.75.

33. Fixed problem of redfish/v1/Managers/1/VM1/CfgCD showing password plain text.
34. Fixed failure to mount VM images after changing VM port over 4 times during Web virtual media mount.
35. Corrected response of setting via in-band interface after setting SMTP sender email.
36. Fixed malfunction of Watchdog setting the pre-timeout NMI interruption after counting down to pre-timeout interval.
37. Fixed problem of Web BMC alert email limiting the number of words.
38. Followed Ultra system to adjust Health event log severity.
39. Fixed problem of Syslog recording a message every 2 minutes.
40. Fixed inability to launch JavaKVM through SMCIPMITool.
41. Fixed failure of 2 SUM ATT test cases.
42. Corrected behavior after updating BIOS through IPMI WebUI.
43. Fixed problem of Redfish returning 500 if request body is empty.

3.68 (4/26/2019)

1. Fixed problem of Redfish returning error 500 after stress Redfish makes get request about 100 times.
2. Updated copyright 2014-2019.
3. Set Redfish scheme to be case insensitive.
4. Added support for LSI 3008/3216/3616 IT management without support for firmware update and logic volume management.
5. Added support for AD/LDAP/RADIUS hostname.
6. Fixed BMC memory leak.
7. Fixed failure to accept the special characters on the share host field.
8. Corrected fan curve for DIMM under standard mode.
9. Set license to activate when Mac changes and OOB source is enabled.
10. Fixed issue of random aux rev sometimes.
11. Fixed failure of BMC remote KVM and remote power control.
12. Fixed problem of IPMITool in-band and out-band hanging because of the special characters &~!@#\$%^*()_-=+{[]|\\;'"<>.>?/ in username and password.
13. Fixed malfunction of top menu refresh link after AD configuration.
14. Fixed problem of IPMI WebGUI receiving "Device @ 0 Group @ 0 Slot @ 0 Removed - Assertion" during AC on/off testing.
15. Fixed missing "Power Source" in IPMI WebGUI Server Health page.
16. Fixed problem with title alignment adjustment on Web pages after firmware update.
17. Fixed problem of IPMI wrongly parsing PCIe correctable error to other description.
18. Fixed problem of Time Stamp displaying 1970/01/01 in health event log during AC on/off test.
19. Added support for the UEFI PXE boot device via Redfish.
20. Fixed inability of SUM to trigger BMC to execute PCH reset action when SPS is downgraded.

