BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| Product Name | H12DSG-O-CPU |
|------------------------|---|
| Release Version | 2.0 |
| Release Date | 03/12/2021 |
| Build Date | 03/12/2021 |
| Previous Version | 1.3 |
| Update Category | Recommended |
| Dependencies | IPMI firmware 1.00.32 |
| Important Notes | BIOS Image:BIOS_H12DSGO-1B55_20210312_2.0_STDsp.binBIOS Update Package:BIOS_H12DSGO-1B55_20210312_2.0_STDsp.ZIPNotice:1) BIOS R 2.x supports 7002 and next generation processor.Flash Utility in the package supports BIOS update from R 1.x to R 2.xonly, cannot roll back. |
| Enhancements | Changed BIOS revision to 2.0. Updated AGESA MilanPI to 1.0.0.1. Updated A011 GN B1 microcode 0A001119. Updated AGESA RomePI to 1.0.0.A. Fixed problem of BIOS initialization showing IPV6 address when IPV6 is disabled in the IPMI GUI. Enhanced SMBIOS Type39 System Power Supply information. Disabled USB OC feature. |
| New features | N/A |
| Fixes | Fixed inability to use F12 hotkey to boot into PXE. Fixed inability to detect AMD GPU cards on Slot7. |

Release Notes from Previous Release(s)

1.3 (12/18/2020)

- 1. Changed BIOS revision to 1.3.
- 2. Updated AGESA RomePI to 1.0.0.9.
- 3. Updated 8310 SSP-B0 microcode 0830104D.
- 4. Displayed TSME, DDR Power Down Enable, PCIe Ten Bit Support, xGMI Link Width Control, xGMI Force Link Width, xGMI Max Link Width Control, xGMI Max Link Width, and xGMI Link Max Speed for GPU performance tuning.

1.2a (11/19/2020)

- 1. Changed BIOS revision to 1.2a.
- 2. Fixed inability of the BIOS to boot to OS/UEFI Shell in assembly house.

1.2 (9/24/2020)

- 1. Changed BIOS revision to 1.2.
- 2. Updated AGESA RomePI to 1.0.0.8.
- 3. Updated help string of item "Input the description".
- 4. Added support for different system configurations.
- 5. Removed Marvell 9230 OPROM from BIOS.
- 6. Updated SMBIOS type 42 data for IPMI Redfish Host Interface support.
- 7. Corrected CPU speed information in BIOS setup.

1.0 (5/26/2020)

Initial Release