

BIOS Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	B12DPT-6
Release Version	1.0b
Build Date	3/17/2021
Previous Version	1.0a
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Updated Intel BKC to WW01. 2. Changed CPU PROHOT pin setting to Input only. 3. Update Intel Microcode to solve correctable UPI errors. 4. Change CPU1 IOU4 bifurcation default setting to X16. 5. Enable CPU1 VMD ports
New features	None
Fixes	1. Corrected inability of NIC1 MAC to display correctly under BMC WebGUI on some boards.