BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| Product Name | X10DGO(-T) |
|-------------------------|--|
| Release Version | 3.3 SPS: 3.1.3.72 |
| Build Date | 2/23/2021 |
| Previous Version | 3.2 |
| Update Category | Recommended |
| Dependencies | None |
| Important Notes | None |
| Enhancements | Changed BIOS revision to 3.3. Updated Intel Microcode: 0x44 for Haswell-EP. Updated Grantley Refresh RC IPU2020.2 to address Intel-TA-00358: CVE-2020-0591 (6.7, Medium) and CVE-2020-0592 (3, Low), and Intel-TA-00390: CVE-2020-8738 (7.5, High), CVE-2020-8740 (6.7, Medium), and CVE-2020-8764 (8.2, High). |
| New features | N/A |
| Fixes | N/A |

3.2 (12/11/2019)

- 1. Updated BIOS version to 3.2 for formal release.
- 2. Updated SINIT ACM 3.1.4 PW for Intel-SA00240 (CVE-2019-0151 CVSS 3.1: 7.5 High).
- 3. Updated Broadwell-EP B0/M0/R0 CPU microcode MEF406F1_0B000038 for Intel-SA00219 (CVE-2019-0117) and Intel-SA00220 (CVE-2019-0123).
- 4. Updated initial value of memory tccd.

3.1c (8/13/2019)

- 1. Updated BIOS version to 3.1c for formal release.
- 2. Updated Haswell microcode to 43 and Broadwell microcode to 36.
- 3. Updated VBIOS to v1.09.00.
- 4. Updated SPS version 05:3.1.3.72.
- 5. Updated module to support new UUID feature.

3.1 (7/30/2018)

- 1. Implemented enhancement to address 'Spectre' variant 2 (CVE-2018-3639 & CVE-2018-3640) security patch issue.
- 2. Updated BIOS version to 3.1 for formal release.
- 3. Added 3-second delay for IPMI PowerSupply FRU command.
- 4. Set Descriptor Region (Bit 0) of BIOS Region Write Access to "No".
- 5. Fixed failure of AOC card (AOC-S3108L-H8iR) Option ROM.
- 6. Fixed failure of DMI writing when cburn is running a test.

3.0a (3/27/2018)

- 1. Implemented enhancement to address 'Spectre' variant 2 (CVE 2017-5715) security patch issue.
- 2. Updated BIOS revision to 3.0a.
- 3. Fixed issue of NVMe M.2 HD hanging at 68h.
- 4. Fixed problem of the default memory RAS mode being named "disabled".