BMC Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	B12DPT-6
Release Version	01.01.02
Build Date	6/14/2021
Previous Version	01.00.18
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Added longer delay and set system to forcefully shut down if graceful
	shutdown fails.
	2. Set yellow RBID notification to show on BMC or BIOS selected
	components.
	3. Set update of BIOS through SUM with BMC reboot to preserve BIOS
	settings.
	4. Disable VM port on first use.
	5. Set completion message to appear for 15 seconds.
New features	1. Added support for AST2600A3.
	2. Added SensorNumber property in /Chassis/1/Thermal.
Fixes	1. Synchronized Alert IP between OEM command and Redfish/Web.
	2. Corrected X-axis unit error in Power Consumption graph in Simplified
	Chinese.
	3. Corrected complex password validation in webUI.
	4. Correctly display user role across motherboard platforms.
	5. Allow storage monitoring to show more than 1 JBOD device.
	6. Correctly display attribute information on storage controller page.

7. Allow memory thermal assertion to cascade CPU thermal event
assertion.
8. Display consistent time formats in Redfish LogServices URIs.
9. Allow user to launch up to 4 HTML5 windows after FD.
10. Include missing sensor reading.
11. Corrected inability to mark the latest event as acknowledged.
12. Corrected severity filtering on Sensor page.
13. Corrected non-functioning scrollbar on multiple pages.
14. Display valid SSDP port number between 1-65535.
15. Corrected inability for the SNMP alerts to be added using
SMCIPMITool.
16. Properly display storage Redfish API count.
17. Correctly display power status displayed after BIOS update.
18. Correctly interpret and trigger VBAT value thresholds.
19. Allow add-on card temperature names containing miscellaneous
characters in SMCIPMITool.
20. Disallow usernames with invalid characters.
21. Corrected IPMI configuration and License activation page button
behavior.
22. Corrected multiple pages where error messages overlaps and/or
obstructs other fields.
23. Corrected Redfish license check.
24. Disallow deleting ADMIN account.
25. Present consistent chassis information on IPMI webUI and FRU CT.
26. Corrected inability to disable IPMI Web SNMPv3.
27. Corrected typo in Redfish driver property.
28. Remove prompt appearing when trying to change Rollback ID
setting on any license other than DCMS.
29. Prevent special characters in Users/Password on Virtual CD-ROM
page.
30. Show full memory serial numbers.

31. Display "Export to excel" string display within frame on HEL/MEL
page in Japanese locale.
32. Properly show error message when typing in IPv4 format address on
IPv6 DNS server field.
33. Corrected some non-English translation errors/spelling.
34. Corrected PSU page formatting/layout.
35. Corrected inability of SMCIPMITool to show IPv6 address after
setting Network LAN mode to dual.