Notes to Release Notes Authors

- All fields <u>must</u> be completed; please indicate as "N/A" if not applicable.
- Release Notes <u>should</u> document functional changes, dependencies, bug fixes and added features.
- Release Notes <u>must not</u> mention the methods of implementation and/or internal processes.
- Release Notes <u>must not</u> mention of silicon errata and/or other external causations.
- Release Notes <u>must not</u> mention confidential/proprietary information and/or trade secrets <u>of Supermicro or any third party</u>.
- Please delete this page and the signature fields before submitting the document in <u>PDF</u>
 <u>Format</u> to Marketing for publication.

IPMI Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12QCH+
Release Version	0.23.32
Build Date	24/4/2021
Previous Version	0.23.26
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	 Fixed missing event log and alter for CPU overheat. Fixed missing Console Capture tap on troubleshooting page.

Release Notes from Previous Release(s)

0.23.26 (1/29/2021)

- 1. Fixed problem of 5VSB Temperature error appearing in the event log when updating IPMI to 00.23.25, then unplugging and plugging in AC.
- 2. Fixed failure of X12QCH+-P Redfish automation test.

0.23.19 (11/11/2020)

- 1. Moved label that was in front of Launch SOL function.
- 2. Fixed failure of test for RSC-D2R-668G4 multi sensor reading function.
- 3. Fixed mismatch of the location of SERR/PERR event log.
- 4. Corrected temperature displayed in AOC/AIOM card sensor reading.
- 5. Fixed missing information when inserting AOC-S100G-b2C in the IPMI GUI.
- 6. Fixed missing sensor reading when inserting AOC-S100G-b2C in the IPMI GUI.
- 7. Fixed failure of DC on/off test and problem of the system displaying 5VSB "Upper Critical going high Assertion".
- 8. Fixed failure of AC on/off test.
- 9. Fixed problem of M2_SSD2 Temp disappearing when running HDD stress.
- 10. Fixed failure of SUM automation test.
- 11. Fixed failure of SATC Redfish automation standard mode test.
- 12. Fixed problem of the front panel information LED blinking when power failure alert deassertion occurs.
- 13. Fixed malfunction of Open iKVM via Remote Console monitor on Dashboard page when pressing monitor a second time.
- 14. Fixed inability of IPMI GUI event log to switch to more than two pages.

Product Manager	 Date	