# **BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPG-QT6
Release Version	1.2
Release Date	02/14/2022
<b>Build Date</b>	02/14/2022
Previous Version	1.1
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1.[Enhancements] Update AMI
	5.22_WhitleyCrb_0ACMS_ICX_070_BETA RC27P52 for BKC
	2021_WW52 (PLR1)
	4.[Enhancements]Change string "VMX" to "Intel Virtualization
	Technology".
New features	N/A
Fixes	1.[Fixes] Remove 1G option from MMCFG base to avoid system hang.
	2.[Fixes] Fixed the SMBIOS event log ERROR CODE not display
	correctly under BIOS menu issue (EFI error type).
	3.[Fixes] Correct "PCIe ASPM Support (Global)"" default value to
	disable.

### 6.[Fixes]Rollback VROC SATA/sSATA EFI driver to VROC PreOS

v7.6.0.1012 to fix system hang when VMD enable.

#### Release Notes from Previous Release(s)

#### 1.1 (04/09/2021)

- 1.[Enhancements] Updated BIOS ACM 1.0.9, SINIT ACM 1.0.9
- 2.[Enhancements] Updated SPS 4.4.4.53.
- 3.[Enhancements] Update SATA/sSATA EFI driver to VROC PreOS v7.5.0.1152.
- 4.[Enhancements] The system cannot boot into PXE with DVD installed.
- 5.[Enhancements] Keep setup string of BiosVersion, BiosDate, Manufacturer and Product as default value including modification of AmiBcp.
- 6.[Enhancements] Add code to stop AFU support.
- 7.[Enhancements] Default enable BootGuard function.
- 8.[Enhancements] Extend memory DIMM serial number information.(Samsung, Micron, Hynix)
- 9.[Enhancements] Enhance Smc Dcpmm feature.
- 10.[Enhancements] Automatically disable and grayed out ADDDC, UMA-Base Clustering, mirror mode and enable NUMA when SGX enabled.
- 11.[Enhancements] Remove intel lan memory 4G limit if boot mode is not legacy.
- 12.[Enhancements] Set all oprom control items to Legacy when boot mode set to Dual.
- 13.[Enhancements] Update for 20P95 LB62 PreDrop V1 for BKC WW15 (20P95)
- 14.[Enhancements] Update Intel-Generic-Microcode-20210226a\_NDA and Intel AE (updated)
- 15.[Fixes] Fix "Configuration Address Source" always show "DHCP" in IPMI IPv6 page.
- 16.[Fixes] Fix Memory correct error location is wrong in BIOS event log for CPU2.
- 17.[Fixes] Modify Ipv6 behavior, remove error message when Ipv6 router IP is ::::::
- 18.[Fixes] Correct CPU1 memory type 20 handler point to CPU2 Memory Array Mapped Address structure
- 19.[Fixes]Fix IPv6 Status show incorrect after updating BIOS.
- 20.[Fixes] Fixed IPv4 address source status show incorrect after updating BIOS issue.
- 21.[Fixes] Fixed the HDD security menu will not show when connect more than 6 HDD on system.
- 22.[Fixes] Fix IPV6 disable in the IPMI GUI but BIOS initialize will appear IPV6 address..
- 23. [Fixes] Filter Dynamic HDD Security Pages to patch SUM ChangeBiosCfg failed problem.
- 24.[Fixes] Fixed UEFI OS boot option name shows incorrectly in BIOS setup.
- 25.[Fixes] Fix T-states always show 15 levels even T-state is disabled.

## 1.0 (12/02/2020)

1. First Release.