

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12SPG-NF
Release Version	1.2 SPS 4.4.4.62
Release Date	2/15/2022
Build Date	2/15/2022
Previous Version	1.1c
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Updated AMI 5.22_WhitleyCrb_0ACMS_ICX_070_BETA RC27P52 for BKC 2021_WW52 (PLR1), and RC27P56 for PLR1 HF.2. Changed text string "VMX" to "Intel Virtualization Technology".
New features	N/A
Fixes	<ol style="list-style-type: none">1. Removed 1G option from MMCFG base to avoid system hang.2. Fixed the SMBIOS event log ERROR CODE that is not displaying correctly under BIOS menu (EFI error type).3. Rolled back VROC SATA/sSATA EFI driver to VROC PreOS v7.6.0.1012 to fix system hang when VMD is enabled.

Release Notes from Previous Release(s)

1.1c (11/12/2021)

1. Updated 5.22_WhitleyCrb_OACMS_ICX_069 Beta Intel BKCWW39 2021 PV MR7, please check header for firmware revisions.
2. Updated Dx/Mx microcode from Intel-Generic-Microcode-20210927_NDA.
3. Extended NVMe OPROM control options to 24 slots.
4. Enabled shutdown suppression and log MCA IERR to fix crash dump error.
5. Removed default support for the certificates CA-Cert, Client-Cert, and Private-Key.
6. Added multiple KMS servers support for SmcKMS.
7. Allowed COM port parameters to be changed in the BIOS settings.
8. Updated BMC boot status to indicate that the ROM is being flashed at a different memory location.
9. Updated SmcOutBand in SmcPKG/Module/SmcOOB to allow the DMI data to be stored when executing "SUM -c LoadDefaultBiosCfg".

1.0 (8/31/2021)

Initial release.