

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2022 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X13DEM</b>
<b>Release Version</b>	<b>1.0a SPS: 6.0.3.271</b>
<b>Build Date</b>	<b>11/02/2022</b>
<b>Previous Version</b>	<b>1.0</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Updated Intel BKC 2022 WW43 (KIT #750947, Intel RC Version 90.D03).</li><li>2. Updated BIOS revision to 1.0a.</li><li>3. Supports SYS-221HE-FTNR system configuration.</li><li>4. Set PCIe PLL SSC enabled value from 0.3% to 0.5%.</li><li>5. Fixed AFU return error so it will stop running when using the /N or /cinevnllog command.</li><li>6. Followed Intel WW36 MOW to disable Pre-GO_S1 setting.</li><li>7. Followed BMC_Network_AOC_Monitoring_Spec_v2.2 to discard the action to send AIOM/AOC IO Module LAN MAC to BMC.</li><li>8. Updated SPS 6.0.3.271 2S PC Hotfix Release for Eaglestream Platforms</li></ol>
<b>New features</b>	<ol style="list-style-type: none"><li>1. Added new feature to set BIOS_EXIT_UBOOT/BIOS_BOOT_OK at end of POST.</li></ol>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Fixed SST function, not work issue.</li><li>2. Fixed the memory serial number of SMBIOS type 17, did not match memory DIMM bar code.</li></ol>