

IPMI Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPT-B6
Release Version	01.02.56
Build Date	1/12/2023
Previous Version	01.02.44
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Enabled StatelessAddressAutoConfig in Redfish Ethernet interface.
New features	1. Added Redfish method to set BMC LAN interface.
Fixes	1. Updated network hostname format. 2. "MEL shown to fail when bios backup image updated successfully". 3. Fixed error HTTP message format at X13 and X12 Redfish (/redfish/{string}.IKVM). 4. When NTP is disabled, the user cannot modify the timezone from the web. 5. Set the HTML5 console as the default selection. 6. IPv6 auto-config option will be enabled after setting other network parameters. 7. Removed rollback ID configuration page. Rollback ID always updates when the firmware updates. 8. Lost PFR image version on the web. 9. Failed to install OS by Virtual Media HTML5 sometimes. 10. New added IPV6 addresses are unavailable. 11. Fixed BMC reset for new SSL certificate to take effect.