

## BMC Firmware Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X13DEG-OA</b>
<b>Release Version</b>	<b>1.00.40</b>
<b>Build Date</b>	<b>1/04/2023</b>
<b>Previous Version</b>	<b>N/A</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>None</b>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. WebGUI CPU Speed info feature broken in 01.00.39.</li><li>2. Fixed sensor controls that show incorrect fan zone values.</li><li>3. Changed sensor name for AOM-PTG-i2T.</li><li>4. Fixed GPU does not report PWM, and the GPU would not control fan speed.</li><li>5. No H100 GPU temperature sensor reading in IPMI.</li><li>6. IPMI does not show the PLX sensor.</li><li>7. IPMI does not show any GPU sensor.</li><li>8. The "Eject" function via IPMI doesn't work on NVMe slot #2 and slot #3.</li></ol>