

BMC Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPT-B6
Release Version	01.02.64
Build Date	3/27/2023
Previous Version	01.02.56
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none">1. Modified the data length check of the OOB preserve command - 0x30 0xA0 0x15.
New features	None
Fixes	<ol style="list-style-type: none">1. BMC 1.02.55 failed to auto-switch SAS controller i2c mode into PCIe mode.2. All sensors drop during DC On/Off testing.3. Wrongly cleared the preservation selection while clicking the Power switch on the top right side.4. HDD monitoring is missing during cburn on/off stress testing.5. Corrected UUID format.