

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| | |
|-------------------------|--|
| Product Name | X13SEI-(T)F |
| Release Version | 1.3a |
| Release Date | 06/02/2023 |
| Build Date | 06/02/2023 |
| Previous Version | 1.1 |
| Update Category | Recommended |
| Dependencies | None |
| Important Notes | None |
| Enhancements | <ol style="list-style-type: none">1. Updated the revision to 1.3a.2. Updated Intel BKC SPR 2023_WW13 PLR1, EMR 2023_WW19, Intel RC Version 101.D66.3. Enhanced the No Bootable Device message on the POST screen.4. Changed the strings from "Lock mode" to "Lockdown mode."5. Set the PPIN default value to Unlock. |
| New features | N/A |
| Fixes | N/A |

Release Notes from Previous Release(s)

1.1 (01/19/2023)

- 1. Updated revision to 1.1.*
- 2. Updated AMI label to 5.29_EagleStreamCrb_0ACOR_071_BETA.*
- 3. Updated SPS 6.0.4.25 2S PV Hotfix Release for EagleStream Platforms.*
- 4. Updated 806F8 Intel(R) Processor SPR E-Stepping microcode 2B000161.*
- 5. Followed the latest BIOS setup template to hide UPI3 in setup for UP projects.*
- 6. Exposed "CXL Security Level" and "CXL Header Bypass" for CXL.*
- 7. Enabled PRM module and updated PrmPKG from EIP724445.*

1.0 (10/11/2022)

- 1. First release.*