

IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SSM-F
Release Version	1.68
Build Date	8/10/2023
Previous Version	1.67
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	<ol style="list-style-type: none">1. Security Fixes: CVE-2023-40289, CVE-2023-40284, CVE-2023-40287, CVE-2023-40288, CVE-2023-40290, CVE-2023-40285, CVE-2023-402862. The BMC FW couldn't pass the production sign check.3. No error message is prompted when using spaces in an IP Access Control rule.4. 404 return code after canceled FW upgrade in progress.