## **BMC Firmware Release Notes**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13DGU
Release Version	1.01.05
Build Date	10/04/2023
Previous Version	1.00.55
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol> <li>HTML5 Console as default.</li> <li>Dual mode for network setting as default.</li> <li>Virtual media supported three CD/FLOPPY image mounting.</li> </ol>
New features	1. Disabled IPMI Lan Port Interface.
Fixes	1. No MEL generated after SNMPv2 is disabled.
	2. No related MEL when disabling TSIG Authentication.
	3. IPv4 DNS setting comparison wasn't the same after executing "ChangeBmcCfg"
	<ol> <li>WEB – Alert dialog doesn't disappear when navigating to the License page via license tip.</li> </ol>