## **BMC Firmware Release Notes**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| Product Name     | X13DET   |
|------------------|--|
| Release Version  | 1.02.03  |
| Build Date       | 11/18/2023   |
| Previous Version | 1.01.07  |
| Update Category  | Recommended  |
| Dependencies     | None   |
| Important Notes  | None   |
| New features     | 1. Added Property "Product" for /redfish/v1.                   |
| Enhancements     | 1. OpenJDK support.  |
|                  | 2. Enabled USB LAN 2 options feature in webUI.                 |
|                  | 3. Support KCS disable function.                               |
|                  | 4. Support LDAP StartTLS.                                      |
| Fixes            | 1. RoT State shown as disabled after factory reset.            |
|                  | 2. BMC Host Interface unexpectedly "Disabled".                 |
|                  | 3. Added MEL after changing Host Interface "RNDIS Connection"  |
|                  | or "CDC-ECM Connection".                                       |
|                  | 4. Unable to load SMTP page.                                   |
|                  | 5. Issue with NULL users not displayed on Accounts page.       |
|                  | 6. Notifications (SNMP) on the Help page are inconsistent with |
|                  | Actual WEB page.   |
|                  | 7. PATCHing  |
|                  | '/redfish/v1/Chassis/StorageBackplane/Drives/Disk.Bay.0'       |

| status code should be 405.<br>8. Resolve SMCIPMITOOL managing IPV6 and DNSv4. |
|---|
| 8. Resolve SiviCIPIVITIOUL managing IPV6 and DNSV4.                           |
|   |
| 9. Validate Access with OOB and No License should switch to                   |
| newer UI behavior.  |
| 10. The NVMe temperature sometimes be incorrect.                              |
| 11. Fixed Systems LogService entry empty data.                                |
| 12. Adding ACCEPT/DROP rules with duplicate IP Address/Mask                   |
| will get blocked.   |
| 13. Unable to connect virtual media when only setting up 1 or 2               |
| virtual connections.  |
| 14. MEL is incorrect when modifying IPV4 DNS Server2 IP.                      |
| 15. Unable to save valid static IPv4 address.                                 |
| 16. IPMI shows system's power consumption too low.                            |
| 17. No U.2 NVMe temperature shown when some NVMe drives are                   |
| installed.  |
| 18. No main menu on IPMIWeb when using iPhone to open                         |
| IPMIWebGUI.   |
| 19. Failed to block download BIOS/BMC Evidence with No License.               |
| 20. Virtual Media is able to add duplicates, three items with the             |
| same Share Host and Path to Image.  |
| 21. Cannot disable Dynamic DNS if TSIG is enabled, have to disable            |
| TSIG first.   |
| 22. Unable to display IPv6 link local address.                                |
| 23. Unable to patch NTP options through Redfish.                              |
| 24. Miscellaneous webUI inconsistencies/errors.                               |
| ·····, •····  |
| 25. Account privilege inconsistencies.  |
| 26. Inconsistent, missing MEL entries.  |
|   |