

# BMC Firmware Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12DPFR-AN6</b>
<b>Release Version</b>	<b>1.03.09</b>
<b>Build Date</b>	<b>11/10/2023</b>
<b>Previous Version</b>	<b>1.01.44</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. [Account Services][LDAP] Support StartTLS.</li><li>2. Modified Dedicated Link options: Added 1G Full and removed 10M Half/Full except X12STD-F and X12STE-F.<ol style="list-style-type: none"><li>a. X12STD-F Dedicated Link is fixed in Auto Negotiation.</li><li>b. X12STE-F Dedicated Link is fixed in 1G Full.</li></ol></li></ol>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. [IPMI 01.01.04] Redfish SATC automation test has failed.</li><li>2. WEB – BMC version is incorrect in the Troubleshooting Log.</li><li>3. Disabled IPMI Lan Port Interface.</li><li>4. [MultVM] Virtual media support 3 CD/FLOPPY image mounting.</li><li>5. HTML5 Console as default.</li><li>6. Dual mode for network setting as default</li><li>7. [IPMI ECO 01.03.07] UID LED should be blinking but keep solid on when using WebUI UID Control.</li><li>8. Fixed fanFAIL feature broken from 01.03.01 to 01.03.06.</li></ol>