

## BIOS Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |  |
|-------------------------|--|
| <b>Product Name</b>     | <b>B11DPE</b>  |
| <b>Release Version</b>  | <b>4.2</b>   |
| <b>Build Date</b>       | <b>12/27/2023</b>  |
| <b>Previous Version</b> | <b>4.0</b>   |
| <b>Update Category</b>  | <b>Recommended</b>   |
| <b>Dependencies</b>     | <b>None</b>  |
| <b>Important Notes</b>  | <b>None</b>  |
| <b>Enhancements</b>     | <ol style="list-style-type: none"><li>1. Updated AMI label 5.14_PurleyCrb_0ACLA061 for RC0628.P59 IPU 2024.1 for AMI Security Advisories SA50191, SA50193, SA50197, SA50198, and SA50205.</li><li>2. Updated Cascade Lake-SP CPU PV microcode for IPU 2024.1.</li><li>3. Updated SA50216_Supplement(LogoFAIL Vulnerability).</li></ol> |
| <b>New features</b>     | <b>None</b>  |
| <b>Fixes</b>            | <b>None</b>  |