

BMC Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X13DEM
Release Version	1.02.29
Build Date	4/8/2024
Previous Version	1.02.22
Update Category	Recommended
Dependencies	None
Important Notes	<ul style="list-style-type: none">• SMC-2024010010 Command Injection attack• SMC-2024010011 XSS attack• (CVE-2023-33413) SMC-2024010012 Command Injection attack• The BMC configuration file generated in BMC firmware older than Rev. 1.01.14 can't be imported.
Enhancements	None
New features	<ol style="list-style-type: none">1. [ENGINEERING] – Upgraded SEL to 1.38 and merged SEL search method to one function.2. [ENGINEERING] – Upgraded MEL to 1.07 and added MEL 70&368. Recorded wrong MEL number when uploaded IPMI config unsuccessfully.3. [ENGINEERING] – Redfish support BMC each field v1.33/ v1.34.
Fixes	<ol style="list-style-type: none">1. [ENGINEERING] Web UI Prompts – 11162023.2. [ENGINEERING] – Supported AOC-E810-XXVDA4.

	3. IPv4/IPv6 help page description is inconsistent with UI Spec definition.
--	--