

BMC Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPT-B6
Release Version	1.04.16
Build Date	4/26/2024
Previous Version	1.04.02
Update Category	Recommended
Dependencies	None
Important Notes	<ul style="list-style-type: none">SMC-2024010010 Command Injection attackSMC-2024010011 XSS attack(CVE-2023-33413) SMC-2024010012 Command Injection attackThe BMC configuration file generated in BMC firmware older than Rev. <revision #> can't be imported.
Enhancements	None
New features	<ol style="list-style-type: none">[ENGINEERING] - Supported AOC-S400G-B1C.
Fixes	<ol style="list-style-type: none">[ENGINEERING] - VirtualMedia does not allow domain URL with port.BMC firmware v01.04.09, IKVM function-bar is not working at all.[ENGINEERING] - X12 ALL sensor N/A in BMC 01.04.15.