

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H13SSH
Release Version	01.03.21
Release Date	08/29/2024
Previous Version	01.03.09
Update Category	Recommend
Dependencies	N/A
Important Notes	<p>ECO # 30466 BMC_H13AST2600-ROT20-E401MS_20240829_01.03.21_STDsp.bin BMC_H13AST2600-ROT20-E401MS_20240829_01.03.21_STD.zip Please update IPMI with attached Flash Utility in package.</p>
Enhancements	<ol style="list-style-type: none">1. Redfish should allow external account service password length more than 202. High temperature management of BlueField-33. Adjust smartnic url index4. Add smartnic related schema5. Fix SmartNIC update button duplicate issue and word display
New features	N/A
Fixes	<ol style="list-style-type: none">1. Fix Host Interface cannot be restored after reloading ipmi configuration2. When set static IPv6 Address to empty, set any Prefix Length will be reverted to blank after save3. Preserve SSL certificate fail when updating BMC FW4. AC on off 200 times test failed.5. The "Disable KCS" option on the web GUI is missing a space6. Fix operator privilege unable to modify AC Power On Event Log button and FIFO Event Log button in HEL page. Fix - Error occurred when switching on/off "Enable AC Power On Event Log" and "Enable FIFO Event Log". Fix - Advanced Settings status cannot be changed Operator privilege Health Event Log successfully. Fix- Advanced Settings status cannot be changed successfully7. Fix raw get channel authentication capabilities with invalid data length [183388] - IPMITool - Get device id with invalid data length. Fix- IPMITool - Cold Reset With Invalid Data Request. Fix - IPMITool - get chassis capabilities with invalid data length8. Temperature Sensor Display as Drive Slot9. Fix Web -- Hostname field behavior is not follow SW-PM definition when input over 63 characters. Fix- Hostname field behavior is not follow SW-PM definition when input over 63 characters.10. The SOL feature was retired in 2023 H2 at h1211. Fix keeping loading on the Task List page with Safari browser. Fix- Keeping loading on the BMC Reset page with Safari browser. Fix - Keeping loading on the BMC Settings page with

	<p>Safari browser. Fix - Keeping loading on the Account Services page with Safari browser. Fix - Keeping loading on the page with Safari browser.</p> <p>12. Error tips with IPv4 Address keep showing even input value is be changed to valid by switching back to Auto Obtain IP</p> <p>13. Fix Hostname field behavior is not follow SW-PM definition when input over 63 characters. Fix - Hostname field behavior is not follow SW-PM definition when input over 63 characters.</p> <p>14. Add static IPv6 address by raw command (0x30 0x68 0x09), when more than 6 addresses, expected to get different return from BMC/SMCIPMITOOL. Fix- Stateful IPv6 Mode in Auto Configuration Does Not Match Specification</p> <p>15. Update invalid BIOS file on BMC web, error return is not user readable PASS</p> <p>16. FlashBIOS fail after modify SMBIOS data.</p> <p>17. No BIOS & BMC option for Inventory Recover when no License key is activated</p>
--	---

Release Notes from Previous Release(s)

01.03.09 (06/10/2024)

1. Support AMD VPU(Video Processing Unit) MA350
2. Support AOC-E810-XXVDA4
3. Upgrade SEL to 1.38 and merge sel search method to one function.
4. Upgrade MEL to 1.07 and Add MEL 70&368.
5. Redfish support BMC each field v1.33/ v1.34.
6. Support AOC-S400G-B1C.
7. Support NIC CPLD update.
8. Support new feature Each Field v1.33.
9. Support Redfish Upgrade 2021.2, RF1.14.
10. Added RSA2048 key for license server from new IT HSM.
11. Support Enhance help page for Java Ikvm to add OpenJdk information.
12. Upgrade SEL to 1.38 and merge sel search method to one function.
13. Upgrade MEL to 1.07 and Add MEL 70&368.
14. Support AOC-E810-XXVDA4.
15. Support new feature Each Field v1.33.
16. Missing LAN an Active Interface when setting Static IPv6.
17. Storage monitoring missing disk info.
18. Redfish Upgrade 2021.2, RF1.14.
19. Added RSA2048 key for license server from new IT HSM.
20. Enhance help page for Java Ikvm to add OpenJdk information.
21. Redfish support BMC each field v1.33/ v1.34.
22. Fix User is able to upload "TSIG.key" and "TSIG.private" with 0kb file on DDNS page.
23. Fix - Web Function -- It allow class D, E of IPv4 addresses for DNS Server IP setting.
24. Fix Fail to mount iso image with IPv6
25. Fix - MEL-0352 will generate even if non-modify SMTP 'Connection Protocol' and 'Authentication' setting.
26. Fix NVMe BP and AOC_NIC2 sensor lost when execute cburn-r87 DC onoff test item.
27. Fix missing LAN an Active Interface when setting Static IPv6.
28. Fix Bloomberg -- Redfish -- 404 return for NVMeSSD Drive URI.
29. Fix misspelled "necessary".
30. Fix Storage monitoring missing disk info.
31. Fix The power consumption from the BMC sensor readings cannot exceed 2044.
32. Fix filter out false VR fault alert on CPU2.
33. Fix Temperature CPU Temp | Upper Critical going high | Asserted | Reading -1 > Threshold -1 degrees C.
34. Fix EventService RedfishEventHttps allow self-signed CA.
35. Fix Redfish 2021.2 failed to GET /redfish/v1/UpdateService/FirmwareInventory/Backplane_1_CPLD_1.
36. Fix user is able to upload "TSIG.key" and "TSIG.private" with 0kb file on DDNS page.
37. Fix Web Function -- It allow class D, E of IPv4 addresses for DNS Server IP setting.
38. Fix Fail to mount iso image with IPv6.
39. Fix MEL-0352 will generate even if non-modify SMTP 'Connection Protocol' and 'Authentication' setting.
40. Fix NVMe BP and AOC_NIC2 sensor lost when execute cburn-r87 DC onoff test item.
41. Fix Bloomberg -- Redfish -- 404 return for NVMeSSD Drive URI.
42. Fix Misspelled "necessary".
43. Fix temperature CPU Temp | Upper Critical going high | Asserted | Reading -1 > Threshold -1 degrees C.
44. Fix EventService RedfishEventHttps allow self-signed CA.
45. Fix edfish 2021.2 failed to GET /redfish/v1/UpdateService/FirmwareInventory/Backplane_1_CPLD_1.

01.02.14 (01/23/2024)

1. The CPU sensor reading became "0" during DC on off stress
2. Prompt will now show in Redfish and Web GUI whenever RBID increase has been detected on uploaded firmware.
3. Enhance GPU Redfish API value.
4. RoT State changed to disabled after factory reset.
5. BMC Host Interface becomes "Disabled".
6. Added MEL after changed Host Interface "RNDIS Connection" or "CDC-ECM Connection".
7. Nvidia L40 GPU no sensor and information.
8. OpenJDK support.
9. Support NVIDIA RTX 4000 Ada, RTX 5000 Ada, RTX 6000 Ada.
10. Add Super Diagnostics Offline in Redfish.
11. Add Property "Product" for /redfish/v1.
12. Enable USB Lan 2 options feature (WEB).
13. Fix system can't eject any device when select all.
14. Fix need SW team to define BMC rules for all SKUs if missing 'CPU Temp'.
15. Fix Virtual Media SMB not support mount with port.
16. Fix PSU health status is abnormal when remove power cord.
17. Fix Sensor naming doesn't match the spec.
18. Fix Should not be able to set invalid ipv6 dns values using SMCIPMI Tool raw commands.
19. Toggling the system power will create repeated "Host FW password has been removed / auto-generated" entries in the MEL.
20. Fix string not match with LAN mode naming.
21. Fix Notifications(SNMP) in Help page is inconsistent with Actual WEB page.
22. Fix SUM -- Failed to Set LAN Auto Configuration DHCPv6Mode Configuration.
23. Fix Unable to load SMTP page.
24. Fix Redfish test fail on Check Account Service Accounts Method Privileges due to unexpect status code return.
25. Fix There is an extra backplane object on BMC "Firmware Management" page.
26. Fix Operator can not have Full Access to Event Log.
27. Fix PATH '/redfish/v1/Chassis/StorageBackplane/Drives/Disk.Bay.0' status code should be 405 but it is 400.
28. Fix MEL is incorrect when restore to factory default.
29. Fix Logging out with enabled SMTP alert will create three MEL entries.
30. Fix Null user test failed, created null users are not displayed on users page.
31. Fix SUM -- Failed to Set LAN Auto Configuration DHCPv6Mode Configuration.
32. Fix [MEL-0093] string not match with LAN Interface option naming.
33. Fix IPV6 -- Fail to set Alternative DNS server IP through SMCIPMITOOL.
34. Fix Validate Access with OOB and No License should switch to newer UI behavior.
35. Fix the X12X13_BMC_UI_Spec specification does not define the "Security Icon" and "Security Page" of ROT 2.0.
36. Fix Redfish Inconsistency.

01.01.23 (10/24/2023)

1. Hostname update/remove has duplicate record in MEL
2. Keep unique password when restore IPMI config
3. Perform the "-lani 0" command on X13DET-B will show the error message "Failed to set the LAN interface. Completion Code=FFh"
4. Redfish has 3 TC fails
5. Username string length only support to 16 not 31 for SNMPv3
6. "Edit" and "Connect" icon should be translated to Simplified Chinese and Japanese at Virtual Media page.
7. Some function of Account Services/Network/BMC Settings could be configurable by "User Privileges".
8. Keep unique password when restore IPMI config
9. Block reserved address when patching IPv6StaticAddresses property of EthernetInterfaces
10. AOC-S25GC-i2S thermal sensor will lose when execute dc onoff test item
11. User only can enter 63 characters for SNMPv3 Authentication Key and Encryption Key
12. IPMI ECO Automation tests Failure
13. Username string length only support to 16 not 31 for SNMPv3
14. Sensors changed abnormally once sensor type category is selected
15. The order of LAN Interface on WebUI not follow SPEC
16. Hot plug issue in both Windows and Linux OS
17. System hang on POST code "A2" after executing AC on/off

01.01.13 (08/31/2023)

1. Fix RMCP connection lost during SPM test
2. no U.2 NVMe temperature when install INTEL SSDPE2MD800G4
3. Connect button doesn't work at Virtual Media page.

- 4. IPMI ECO redfish automation has 4 fails
- 5. VLAN Tagging test failed
- 6. IP Access Control page can be edited/deleted by user privileges

01.01.07 (07/10/2023)

- 1. Hostname update/remove has duplicate record in MEL
- 2. Keep unique password when restore IPMI config
- 3. Perform the "-lani 0" command on X13DET-B will show the error message "Failed to set the LAN interface. Completion Code=FFh"
- 4. Redfish has 3 TC fails
- 5. Username string length only support to 16 not 31 for SNMPv3
- 6. "Edit" and "Connect" icon should be translated to Simplified Chinese and Japanese at Virtual Media page.
- 7. Some function of Account Services/Network/BMC Settings could be configurable by "User Privileges".
- 8. Keep unique password when restore IPMI config
- 9. Block reserved address when patching IPv6StaticAddresses property of EthernetInterfaces
- 10. AOC-S25GC-i2S thermal sensor will lose when execute dc on/off test item
- 11. User only can enter 63 characters for SNMPv3 Authentication Key and Encryption Key
- 12. IPMI ECO Automation tests Failure
- 13. Username string length only support to 16 not 31 for SNMPv3
- 14. Sensors changed abnormally once sensor type category is selected
- 15. The order of LAN Interface on WebUI not follow SPEC
- 16. Hot plug issue in both Windows and Linux OS
- 17. System hang on POST code "A2" after executing AC on/off

01.01.06 (06/28/2023)

- 1. AOC thermal sensor lose when run DC ON/OFF .
- 2. IPMI ECO Automation tests Failure (TC4010)
- 3. IPMI cannot detect the U250 sensor
- 4. Fixed Login RADIUS account issue.
- 5. IPMIECO Automation test failed (Networking)
- 6. During System Lockdown, Date and Time Auto Daylights Savings Time switch is not disabled when it should be.
- 7. "background-color" of input field on both "Network" and "Port" tabs are as same as page background.
- 8. Operator health event log advanced settings disabled; License activation Upload button enabled for admin even when no private key file is selected; and one more...
- 9. The content loss and incorrect of Share LAN when set option to "Shared-AIOM2" , " Shared-AOC" , " Shared-AIOM1".
- 10. "Enable TSIG Authentication" switcher doesn't disable when DDNS is off.
- 11. Failed Login Attempt Lockout Threshold radio buttons aren't all disabled for Operator and User privilege.
- 12. Power state ICON not refresh after power cycle complete.
- 13. Syslog packet not follow RFC3164

01.01.04 (06/09/2023)

- 1. Upgrade the EthernetInterface version from v1.6.2 to v1.6.3 to align spec.
- 2. Dark Theme update
- 3. Support new Intel PVC GPU (DID: 0x0BDA)
- 4. BMC networking issues
- 5. Radius packet not follow RFC2865"
- 6. Authentication Protocol and Encryption Protocol Range setting is not match Wiki SPEC.
- 7. The error message incorrect when launch more than 4 iKVM sessions.
- 8. VM cannot save valid IPv6 address with port.
- 9. iKVM default setting is not HTML5 after factory default.
- 10. "Number" should be translated to Simplified Chinese and Japanese at Virtual Media page.
- 11. "Export to Excel" button should be translated to Simplified Chinese and Japanese at Sensor page.
- 12. User name string length only support to 16 not 31 for SNMPv3.
- 13. Auto Daylight Savings Time switcher doesn't disable for the Operator and User privilege.
- 14. Enable a prompt window similar to the one for switching on lockdown mode.
- 15. BIOS automation TC 5006 failed
- 16. Unable to display information when the LAN interface is in shared mode.

01.01.03 (05/26/2023)

- 1. Retrieve BIOS version from 'OFID'
- 2. KVM launched and closed MEL should display user ID
- 3. Support BPN-NVME5-HS219N-S24 SATA mode on JRSI2C1

4. Auto Daylight Saving Time
5. Task Queue & Task List
6. Redfish 2020.3 related feature
7. Buttons and icons of Virtual Media page can operate while System Lockdown enable
8. With HBM CPU, only partial memory modules are listed in IPMI Web GUI memory info
9. Fixed BMC GUI sensor arrangement order is not stable.
10. Fixed VM mount issue
11. Fixed IPMI Lan set ipsrc for dhcp to static IP missing.
12. Fixed Unable to close popup window under System lockdown mode
13. AD related MEL should not shown when setup LDAP and Radius
14. User is able to click delete button on system lockdown mode
15. Fixed DMTF/Redfish standard API support test failed
16. Webgui crashed after uploading product key with invalid file
17. Fail to use SecureErase with SAS 3816 IR card
18. IP changed after running raw command
19. Network Setting Page Can Now Save With Only 1 Dedicated LAN Speed Capability
20. System Lockdown Storage Monitoring Physical View buttons are enabled
21. [Redfish] expect length of Service Addresses to be 1 but is actually 3
22. Change BIOS password fail
23. MEL Log msg is incorrect when configure Syslog.
24. Fixed chassis intrusion reset button not grey out issue when System Lockdown Mode is on
25. AOC-S25G-m2S sensor temp drop

01.00.36 (04/14/2023)

First release