

BMC Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DDW-A6-P
Release Version	01.04.13
Build Date	8/27/2024
Previous Version	01.04.04
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	None
New features	None
Fixes	<ol style="list-style-type: none">1. Fixed unexpected "The path of Process sshd is not correct" MEL message. Updated tee.bin to 0000.00.32.2. Upgraded OpenSSH from 9.3p2 to 9.8p1.3. WebUI – TC4017 – Fixed IPMI IP will be replaced or lost. CombinedECO SAA – TC0005 – Connection through dedicated LAN with static IP. CombinedECO SAA – TC0007 – Connection through on-board LAN1 with static IP.4. The MEL displayed when adding and deleting user via UI and SMCIPMITool does not match "[MEL-0000] Local user ID _ _ _ was added successfully." and "[MEL-0002] Local user ID _'s name was configured to _ _ _ successfully."