

## BMC Firmware Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12DPT-B6</b>
<b>Release Version</b>	<b>1.05.17</b>
<b>Build Date</b>	<b>10/15/2024</b>
<b>Previous Version</b>	<b>1.04.16</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. [ENGINEERING] — Resumed pending task now possible through Web GUI.</li></ol>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. [ENGINEERING] — Removed Action of ResetToDefault parameter "PreserveNetwork".</li><li>2. [ENGINEERING] — Made PreserveNetwork backward compatible as Redfish 2020.</li><li>3. DDNS accepting invalid characters.</li><li>4. [ENGINEERING] — Fixed LAN setting will change when rebooting BMC.</li><li>5. [ENGINEERING] — Updated Fan list sort rule.</li><li>6. [ENGINEERING] — The System button of Dashboard no reaction.</li><li>7. [ENGINEERING] — Updated slot format of Physical Storage view.</li></ol>

	<ul style="list-style-type: none"><li>8. [ENGINEERING] — Adjusted license of OemDumpService.Collect.</li><li>9. DDNS showing incorrect error message.</li><li>10. [ENGINEERING] — WEBUI HDD Temp and SSD Temp show null and correct Drive Status.</li><li>11. [ENGINEERING] — Redfish 2021.2 failed to GET /redfish/v1/UpdateService/FirmwareInventory/Backplane_1_CPLD_1.</li><li>12. [ENGINEERING] — Added RSA2048 key for license server from new IT HSM.</li><li>13. Redfish automation test failed 12 TCs.</li><li>14. [SM2406124458] — Added Customized Page for HTTP status 500.</li><li>15. [ENGINEERING] — M2_SSDx Temp reading is missing.</li><li>16. The network setting Redfish API got 500 error with unrestricted input at X12. DNS setting accepted unrestricted input and return 500 error at B12DPT-6.</li><li>17. [ENGINEERING] — HTML5 and IKVM unstable in BMC 01.05.14. WEBUI response slowed in BMC 01.05.14.</li><li>18. [ENGINEERING] — Modified Redfish EjectMedia and InsertMedia target always displayed on /redfish/v1/Managers/1/VirtualMedia/*.</li><li>19. [ENGINEERING] — Replaced Model of redfish/v1/Managers/1.</li><li>20. [ENGINEERING] — Added LDAP RFC2307bis support.</li></ul>
--	--