

# BMC Firmware Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X14DBG-DAP</b>
<b>Release Version</b>	<b>01.00.13.00</b>
<b>Build Date</b>	<b>2/10/2025</b>
<b>Previous Version</b>	<b>01.00.09.00</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>None</b>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li><b>1. SSM: The serial number for the storage card does not match.</b></li><li><b>2. Set the AOC temperature sensor threshold based on different types of BF3.</b></li><li><b>3. Workaround for MBCPLD2 version might be empty due to BPN CPLD.</b></li><li><b>4. Workaround for MBCPLD2 version might be empty due to BPN CPLD in X14 DBG-DAP.</b></li><li><b>5. Changed "AOM_SASx Temp" to "AOM_SAS Temp."</b></li><li><b>6. Fixed issue with Disable IPv4, but IP still exists.</b></li></ol>