

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H14SST-G
Release Version	01.00.09.00
Release Date	02/04/2025
Previous Version	01.00.06.00
Update Category	Recommended
Dependencies	BIOS 1.3
Important Notes	BMC image: BMC_H14AST2600-ROT-9501MS_20250204_01.00.09.00_STDsp.bin BMC image and flash utility package: BMC_H14AST2600-ROT-9501MS_20250204_01.00.09.00_STDsp.zip BIOS 1.3 and IPMI 01.00.09.00, or newer versions, are required to support AMD EPYC™ 9004 Series Processors.
Enhancements	1. Added support for AMD Turin MCTP bridging.
New features	N/A
Fixes	1. Fixed issue where the BMC event log between SCC and BMC WebUI did not match.
01.00.06.00 (10/18/2024) First release	