

# BIOS Firmware Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>B13DET</b>
<b>Release Version</b>	<b>2.6</b>
<b>Build Date</b>	<b>04/07/2025</b>
<b>Previous Version</b>	<b>2.1</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Updated AMI 5.32_EagleStreamCrb_0ACOR_108_BETA for IPU2025.2.</li><li>2. Updated m_87_c06f2_210002a9 for EMR A stepping CPU.</li><li>3. Updated m_87_806f8_2b000639 for SPR E stepping CPU.</li><li>4. Updated m_10_806f8_2c0003f7 for SPR HBM B stepping CPU.</li><li>5. Updated Intel Server Platform Services SPS_E5_06.01.04.089.</li><li>6. Updated Seamless MCU capsule revision to 2.5.</li><li>7. Updated Secure Boot DBX to address the AMI SA50300 (CVE-2024-7344/CVE-2023-24932 (8.2 High/6.7 Middle)).</li><li>8. Exposed "Enable SAF".</li><li>9. Updated VROC UEFI to 9.0.0.2018.</li></ol>
<b>New features</b>	<b>None</b>
<b>Fixes</b>	<b>None</b>