

## IPMI Firmware / BIOS Release Notes Form

*Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X11SSL(-F)/X11SSM</b>
<b>Release Version</b>	<b>2.1</b>
<b>Release Date</b>	<b>12/11/2017</b>
<b>Previous Version</b>	<b>2.0c</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>N/A</b>
<b>Enhancements</b>	<b>1. Changed BIOS revision to 2.1 for INTEL-TA-201710-003. 2. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v4.7.0.1014. 3. Updated DT_P_140 for Kaby Lake-S B0 stepping MCU M2A906E9_0000007C and Skylake-S R0/S0 stepping MCU M36506E3_000000C2.</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>1. Fixed problem of ACPI Exception: AE_NOT_FOUND occurring.</b>

**Release Notes from Previous Release(s)** – these will be appended at the bottom of the current release notes in italic and in smaller print

N/A