

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H11SSL-I / H11SSL-C / H11SSL-NC
Release Version	1.0a
Release Date	3/2/2018
Previous Version	1.0
Update Category	Critical
Dependencies	N/A
Important Notes	ECO# 20432 BIOS Image H11SSL8.222 Please update BIOS using attached Flash Utility in .zip package.
Enhancements	<ol style="list-style-type: none">1. Added security patch to address 'Spectre' Variant 2 (CVE-2017-5715) security vulnerability.2. Updated AMD AGESA to 1.0.0.5 based on AMI CRB_014.
New features	N/A
Fixes	<ol style="list-style-type: none">1. Fixed problem of using the F11 boot menu with AHCI M.2 device installed causing system to freeze.2. Updated AMI PSPDATA in recovery mode.3. Fixed failure to execute Legacy OPROM when AOC-LSI3008L-L8i is installed in SLOT1 (PCI-E 3.0 x8).4. Added support for AOC.

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

1.0 (1/8/2018)

Initial Release