

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRi-T
Release Version	3.66
Release Date	1/30/2018
Previous Version	3.58
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Improved multi-language content on the iKVM/HTML5 option menu and submenu. 2. Disabled MCTP support on Broadcom 3108 firmware so it only supports I2C protocol. 3. Added support for Redfish firmware inventory (BIOS/BMC update).
New features	N/A
Fixes	1. Fixed failure of SUM "Test_case_215 Outband - ChangeBmcCfg and compare". 2. Fixed inability to disable LDAP Authentication immediately after enabling it. 3. Fixed problem of product serial number being incorrect when it is longer than 15 characters and written in IPMI FRU. 4. Fixed failure of SUM 2.0.1 Test.