

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H11SSL-i/C/NC (All)
Release Version	1.30
Release Date	3/30/2018
Previous Version	1.28
Update Category	Critical
Dependencies	N/A
Important Notes	ECO #20613 IPMI Image Please update IPMI with attached Flash Utility in package.
Enhancements	N/A
New features	N/A
Fixes	<ol style="list-style-type: none">1. Fixed failure of test via ICO/USB.2. Fixed incorrect IPMI FAN mode.3. Fixed failure of Redfish automation tool check.

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

1.30 (2018/03/12)

1. *Fix PBID#87074 test fail via ICO/USB.*
2. *Fix PBID#86070 IPMI FAN mode is not correct.*
3. *Fix PBID#87248 Redfish automation tool check is fail.*

Product Manager

Date