

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SSL-CF/nF
Release Version	2.1a
Release Date	03/9/2018
Previous Version	2.1
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Updated CPU microcode to address 'Spectre' variant 2 (CVE 2017-5715) security issue. 2. Changed BIOS revision to 2.1a. 3. Added support to speed the memory up to 2667Mhz. 4. Added support for UEFI mode PXE boot via F12 hot key Net boot. 5. Added Ramaxel JEDEC Manufacturer ID to support Ramaxel memory.
New features	1. Added support for Intel SGX.
Fixes	1. Fixed issue with IPMI force boot. 2. Fixed problem of system not showing correct manufacturer name or product name when IPMI without FRU1 is programmed. 3. Fixed failure of ATT BIOS ECO test case 237.

	<p>4. Fixed inability to load Broadcom SAS3008 configuration utility.</p> <p>5. Fixed problem of SGX resetting to default value if using SUM to change SGX items after BIOS update</p>
--	--

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print