IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SSV-M4F
Release Version	1.45
Release Date	2/6/2018
Previous Version	1.29
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Improved multi-language content on the iKVM/HTML5 option menu
	and submenu.
	2. Renamed Redfish APIs as follows: from
	/redfish/v1/UpdateService/SSL to /redfish/v1/UpdateService/SSLCert,
	and from /redfish/v1/UpdateService/SSL/Actions/SSL.Upload to
	/redfish/v1/UpdateService/SSLCert/Actions/SSLCert.Upload.
	3. Changed the license requirement of WebGUI syslog from DCMS to
	оов.
	4. Fixed security vulnerability with NTP mode 6 scanner.
New features	1. Added 204 and 405 http status code support for Redfish API so that
	204 http status code responds to APIs that support PATCH and 405 http
	status code responds to APIs that do not support PATCH.
	2. Nested ICANN domain in "OEM" part if there is data to show.
	3. Added Redfish support for new APIs.
	4. Added support for SEL circular buffer.
Fixes	1. Fixed failure of Redfish automation test.
	2. Fixed problem of system showing that IPMI execution exception
	occurred while executing SUM test.

- 3. Fixed problem of the help page of iKVM/HTML5 console not supporting multi-language content and only supporting English.
- 4. Fixed problem of BMC not logging "Thermal Trip" event when CPU overheats before system shutdown.
- 5. Fixed problem with logging in on web page.
- 6. Fixed inability of DCMS mods to enable Syslog function and ability to read Syslog without OOB key.
- 7. Fixed problem of some digit keys not working when French keyboard layout is selected.