

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	C9X299-(R)PGF
Release Version	1.25
Release Date	8/29/2018
Previous Version	0.16
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Improved multi-language content on the iKVM/HTML5 option menu and submenu. 2. Improved the help message descriptions to follow Help Menu Suggestions v1.8.
New features	None
Fixes	1. IPMI shows System Event Log. 2. Corrected abnormal VCPU reading (UNR). 3. Added 3108 sensor reading in WebGUI. 4. IPMI Web detect if user is deleted through SMCIPMITool. 5. Disabling "IPMI Extended Instruction" no longer causes IPMI sensors to go missing. 6. Added default timeout value on Redfish when accessing Manager's ActiveDirectory. 7. Redfish no longer returns 500 and allow patching IP Access Enabled key. 8. Show "Thermal Trip" event in IPMI SEL.