

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X11DPG-SN</b>
<b>Release Version</b>	<b>2.2</b>
<b>Release Date</b>	<b>10/31/2018</b>
<b>Previous Version</b>	<b>2.1</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>N/A</b>
<b>Important Notes</b>	<b>N/A</b>
<b>Enhancements</b>	<b>1. Updated BIOS version to 2.2. 2. Updated RSTe package to v.5.5.0.1028.</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>1. Fixed problem of NVIDIA P4 GPU Loss function after flashing BIOS v2.1.</b>

***Release Notes from Previous Release(s)***

**2.1 (9/17/2018)**

- 1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue.*
- 2. Changed BIOS revision to 2.1.*
- 3. Added code to program CPLD for backplane detection.*
- 4. Updated Intel code to correct issue with NVIDIA P2P bandwidth.*
- 5. Fixed inability to execute UEFI PXE boot with AOC-MGP-i2 and added i350 UEFI Option ROM for X11DPG-SN.*
- 6. Fixed failures of Test Case 220 and 308 Test.*