

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X11DPG-OT-CPU</b>
<b>Release Version</b>	<b>2.1a</b>
<b>Release Date</b>	<b>10/02/2018</b>
<b>Previous Version</b>	<b>2.1</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>1. Changed BIOS revision to 2.1a.</b>
<b>New features</b>	<b>1. Added support for the X11DPG-O-PCIe board.</b>
<b>Fixes</b>	<b>1. Changed MMIO High Granularity size from 256G to 1024G to fix problem of hang 91 occurring with 8x V100 GPU.</b>

**Release Notes from Previous Release(s)**

**2.1 (9/17/2018)**

1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue.
2. Changed BIOS revision to 2.1.
3. Added code to program CPLD for backplane detection.
4. Updated Intel code to correct issue with NVIDIA P2P bandwidth.
5. Fixed inability to execute UEFI PXE boot with AOC-MGP-i2 and added i350 UEFI Option ROM for X11DPG-SN.
6. Fixed failures of Test Case 220 and 308 Test.

**2.0b (2/26/2018)**

1. Implemented enhancement to address 'Spectre' variant 2 (CVE 2017-5715) security patch issue.
2. Updated BIOS version to 2.0b.
3. Added support for IPMI to fix RSC-G2F-A66-X1 sensor reading.
4. Added 2U PLX riser card to support list.
5. Fixed failure of SIOM sensor reading.
6. Fixed failure of IOBP Check.