## **IPMI Firmware / BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10QRH+
<b>Release Version</b>	3.1a
Release Date	10/24/2018
<b>Previous Version</b>	3.1
<b>Update Category</b>	Recommended
Dependencies	N/A
Important Notes	N/A
Enhancements	N/A
New features	N/A
Fixes	1. Fixed inability to enable MCEON setting during BurnIn.

Release Notes from Previous Release(s)	
3.1 (7/5/2018)	
<ol> <li>Updated CPU microcode for Intel security issue.</li> <li>Modified threshold limit of ECC memory to 100.</li> </ol>	
3.0a (3/1/2018)	
<ol> <li>Updated CPU microcode of Broadwell B0, M0, and R0 to version 2A and I version 3C.</li> <li>Updated CPU4 PCIE RX_CTLE_PEAK_GEN3_0 and RX_CTLE_PEAK_GEN3_</li> </ol>	
Product Manager	 Date