

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| | |
|-------------------------|---|
| Product Name | X11SSZ-TLN4F/Q(F) |
| Release Version | 1.52 |
| Release Date | 12/25/2018 |
| Previous Version | 1.41 |
| Update Category | Recommended |
| Dependencies | N/A |
| Important Notes | N/A |
| Enhancements | 1. Changed FirmwareInventory to SmcFirmwareInventory to prevent user confusion with Redfish standard definition. 2. Improved multi-language content on the iKVM/HTML5 option menu and submenu. |
| New features | 1. Added support for TaskService feature during BIOS, BMC, and Broadcom storage controller update in Redfish. 2. Added new feature for GUID/BoardID in Redfish. 3. Added new feature for event data extension in Redfish. 4. Revert MAC address format to "xx:xx:xx:xx:xx:xx" for backward compatibility. 5. Added Redfish Memory Information feature. |
| Fixes | 1. Make SNMP behavior identical to X11DP. 2. Improved GPU Fan control. 3. Multi-language support for iKVM/HTML5 console help page. 4. Return correct completion code to SUM for GetBmcCfg/ChangeBmcCfg commands. 5. Improved web page logging. |