## **IPMI Firmware**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

| <b>Product Name</b> | X11DAI-N   |
|---------------------|--|
| Release Version     | 1.64   |
| Release Date        | 1/16/2019  |
| Previous Version    | 1.53   |
| Update Category     | Recommended  |
| Dependencies        | None   |
| Important Notes     | None   |
| Enhancements        | 1. Changed the naming for "Health Event Log" and "Maintenance        |
|                     | Event Log" in Web UI.  |
|                     | 2. Migrated the IPMI Event Log to the URL                            |
|                     | "redfish/v1/Systems/1/LogServices" in Redfish and changed the        |
|                     | name "Event Log" to "System Management Log" in Redfish and Web       |
|                     | UI.  |
| New features        | 1. Added support for Hynix memory for BMC.                           |
|                     | 2. Enabled clearing all system event logs without generating any log |
|                     | and dumping all the system event logs.                               |
|                     | 3. Added support for BMC Event Log in Redfish and renamed the        |
|                     | function name from "System Event Log" to "BMC Event Log" in Web      |
|                     | UI.  |
|                     | 4. Added support for TaskService feature during BMC and Broadcom     |
|                     | storage controller update in Redfish.                                |

5. Added parameter (SkipCheckingME) for BIOS update in Redfish to skip ME checking. 6. Added support for Redfish SimpleUpdate for BMC and BIOS firmware. 7. Changed FirmwareInventory to SmcFirmwareInventory to prevent user confusion with Redfish standard definition. 8. Revert MAC address format to "xx:xx:xx:xx:xx:xx" for backward compatibility. 9. Added support for saving 3108 storage controller status event. 10. Added support for NIC/GPU Asset Information on Redfish. 11. Added hardware component status in Redfish/WebGUI. 12. Added support for TaskService feature during BIOS update in Redfish. 13. Added support for Node Manager in Redfish. 14. Added new feature for GUID/BoardID in Redfish. 15. Added new feature for event data extension in Redfish. 16. Added OEM event Description and Severity in Redfish/WebGUI. 17. Provided Event Acknowledgment for the events with Warning/Critical severity level. 1. WebUI no longer disappears after selecting simplified Chinese language. 2. DCMS license activation now shows consistent status. 3. Removed "Save uncompleted" message appearing when changing time and saving in IPMI Web. 4. Corrected IPMI SOL failures. **Fixes** 5. Corrected behavior of IPMI Web Date & Time configuration. 6. System status now references PSU state when AC is lost. 7. Corrected issue where Redfish causes a session to timeout after accessing the System Event Log page and BMC to boot loop. 8. AOC NIC Threshold now follows Thermal Guidelines.

- 9. Corrected inconsistent return codes (200, 500, 503) being displayed from the BMC when using ApacheBench.
- 10. Allow removing DNS server IPv6 address.
- 11. Corrected NVMe eject and insert in Event log failures.
- 12. Removed incorrect message appearing on iKVM/HTML5 page when disabling IKVM port.
- 13. Display correct AOC NIC sensor threshold.
- 14. System no longer shows normal when the power fails.
- 15. Corrected Timeout function for graceful shutdown.
- 16. Corrected update SSL certificate file failures.
- 17. Redfish no longer returns 200 when PATCH PowerLimit reaches over 32767.
- 18. Allow NVMe temperature sensor readings to decrease.
- 19. IPMI Web no longer showing system warning after updating firmware.
- 20. Allow IPMICFG and IPMITool to change IPMIIPv6 mode.
- 21. Use consistent BMC MAC address format.
- 22. Improve OEM Event Alert.