

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRi(-T)
Release Version	3.1a ME: 05:3.1.3.38
Release Date	4/16/2019
Previous Version	3.1
Update Category	Recommended
Dependencies	None
Important Notes	N/A
Enhancements	1. Changed BIOS revision to 3.1a. 2. Updated ASPEED VBIOS to version 1.09.00. 3. Updated RSTe SATA/sSATA driver to v6.1.0.1017.
New features	N/A
Fixes	N/A

Release Notes from Previous Release(s)

3.1 (9/14/2018)

- 1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue.*
- 2. Changed BIOS version to 3.1.*
- 3. Updated Intel RC code to v4.4.0.*
- 4. Removed unsupported memory frequency options from setup menu.*
- 5. Changed the CECC Error Threshold Count to 100.*
- 6. Set Descriptor Region of BIOS Region Write Access to "No".*
- 7. Fixed failure of "Wait for F1 if Error" function to work properly.*
- 8. Fixed problem of power supply PWS-865-PQ FRU information showing incorrectly.*

3.0a (2/6/2018)

- 1. Implemented enhancement to address 'Spectre' variant 2 (CVE 2017-5715) security patch issue.*
- 2. Changed BIOS revision to 3.0a.*
- 3. Updated Intel RC code to v4.3.0.*
- 4. Updated Intel BIOS ACM firmware to v3.1.0 and SINIT ACM firmware to v3.1.1.*