

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11DPG-SN
Release Version	1.69
Release Date	4/10/2019
Previous Version	1.64
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Added patch for CVE-2019-6260 pantsdown.
New features	1. Added new support for Uboot code version.
Fixes	1. Fixed issue of changed default passwords not working remotely if they contain !@#\$%^&*. 2. Fixed malfunction of KVM and remote control after using SSH in SMASH with AD account. 3. Corrected performance degradation & unavailable SEL event appearing after Broadcom 3108 firmware is updated. 4. Allow obtaining LSI 3108 I2C temperature sensor. 5. Improved Web UI formatting. 6. Corrected the sensor Qty of BMC. 7. Fixed mismatch of Redfish FullList Allowed Operation. 8. Improved controller health after multiple HDDs are pulled out simultaneously.