

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRU-I+
Release Version	3.80
Release Date	2/14/2019
Previous Version	3.78
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Migrated IPMI Event Log to the URL "redfish/v1/Systems/1/LogServices" in Redfish and renamed the function name from "Event Log" to "System Management Log" in Redfish & Web UI.
New features	1. Patched CVE-2019-6260.
Fixes	1. Removed SEL degraded and unavailable events after Broadcom 3108 firmware is updated. 2. Allow setting NM power policy by Redfish API. 3. Corrected inability to add AD group name and domain in SMCIPMITool. 4. Allow opening Java IKVM when domain name is used to login to BMC. 5. Removed duplicate BRCM3108 events.

Release Notes from Previous Release(s)

3.78 (10/4/2018)

New features

- 1. Revert MAC address format to "xx:xx:xx:xx:xx:xx" for backward compatibility.*
- 2. Added parameter (SkipCheckingME) for BIOS EnterUpdateMode in Redfish to skip ME checking.*
- 3. Added support for TaskService feature during BMC and Broadcom storage controller update in Redfish.*
- 4. Added support for Node Manager feature in Redfish.*
- 5. Added new feature for GUID/BoardID in Redfish.*
- 6. Added new feature for event data extension in Redfish.*
- 7. Changed FirmwareInventory to SmcFirmwareInventory to prevent user confusion with Redfish standard definition.*
- 8. Added support for new Redfish firmware inventory (3108 storage controller) to update firmware.*
- 9. Added support for monitoring Broadcom storage controller 3008/3216 (HBA/Host Bus Adapter) temperature, attached physical drive temperature, and attached physical drive status.*

Fixes

- 1. Allow opening 4th IKVM session in Redfish.*
- 2. Corrected IP address format on System page.*
- 3. Power consumption history no longer shows minimum power as 0W.*
- 4. Misc text formatting.*