

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10SLL+-F/X10SL7-F
Release Version	3.72
Release Date	5/15/2018
Previous Version	3.45
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Revised Redfish "Actions" for clearing event log.
New features	1. Added new Redfish features for downloading and uploading IPMI configuration. 2. Enabled AC Power On Event log. 3. Added Redfish memory information feature.
Fixes	1. Redfish no longer returns 500 when NetworkProtocol is patched after factory default.