

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SRM-VF
Release Version	1.21
Release Date	6/22/2018
Previous Version	1.13
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	<ol style="list-style-type: none">1. Implemented workaround for X11SRM to change GPIOE3 to OpenDrain.2. IPMI sensor no longer disappears after disabling "IPMI Extended Instruction".3. Added Redfish default timeout value for accessing Manager's ActiveDirectory.4. Patching IP Access Enabled key no longer returns 500 Internal Error from Redfish.5. Include "Thermal Trip" event in IPMI SEL.

Release Notes from Previous Release(s)

1.13 (12/5/2017)

- 1. LAN IC temperature & CPU/MEM VRM temperature increase no longer cause fans in zones 1 & 2 to speed up at the same time while in optimal mode.*
- 2. Added U.2 NVMe SSD temperature monitoring.*
- 3. IPMI now shows System Event Log.*