

IPMI Firmware

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SSW-F
Release Version	3.73
Release Date	9/24/2018
Previous Version	3.64
Update Category	Recommended
Dependencies	N/A
Important Notes	N/A
Enhancements	1. Upgraded NTP to version 4.2.8p10. 2. Changed 'event log' to 'health event log' and 'system event log' to 'maintenance event log'.
New features	1. Set LDAP default IP address to show as 0.0.0.0. 2. Enabled AOC MAC address to show on system page without TAS. 3. Added save button to WebUI Server Health->Sensor reading page. 4. Added support for GetSetBMCStatus command for TAS. 5. Synced system MAC and AOC MAC to Redfish without TAS. 6. Set system event log to record most configuring operations. 7. Copied BM/BP/BS from FRU1 to FRU0 if they are empty. 8. Updated Redfish API to 3/16/2018.
Fixes	1. Corrected power history record for some situations. 2. Corrected iKVM not working properly after iKVM reset in certain situations.

	<ul style="list-style-type: none">3. Show No Access User Network Privilege on User page.4. Allow deleting hostname on network page.5. Power history record page no longer times out due to abnormal power peak.6. Corrected power supply FRU being empty in DMI after the AC is first powered on.7. Show chassis intrusion status in IPMITool Chassis Status.8. IKVM reset now closes IKVM console.9. IPMI now returns to login page automatically after reloading IPMI Configuration.10. SMCIPMITool and WebGUI now shows the same values for PSU FAN RPM.11. Corrected port configure page value range.12. LAN configuration and power control no longer fails after BMC VLAN is enabled and LAN mode is changed.13. User name length now has a minimum of 4 characters.14. Active KVM console connections no longer disconnects after launching the maximum of 4 sessions.15. Alert, sensor error status, and blinking error LED now shown when removing power supply.16. Corrected AD/LDAP/RADIUS conflict.17. Hotkeys no longer can be tied to 2 or more different actions.18. Removed irrelevant/duplicate system event logs.19. Corrected SMCIPMITool "pminfo" command.20. Allow saving and restoring syslog configuration via maintenance->IPMI Configuration.21. Validate IP format on IP Access Control page.22. Clearing configuration no longer removes licenses.
--	---