

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SRM-F/VF
Release Version	1.29
Release Date	3/22/2019
Previous Version	1.21
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Patched CVE-2019-6260 pantsdown.
New features	N/A
Fixes	1. Corrected KVM and remote control failures after using SSH in SMASH with AD account. 2. Sessions no longer times out after accessing system event log page and causing BMC boot loops. 3. Redfish returns consistent codes (200, 500, 503) occurring from BMC using ApacheBench. 4. Set default LDAP port to match WebGUI. 5. Remove incorrect message appearing on iKVM/HTML5 page when disabling IKVM port. 6. Allow removing DNS server IPv6 address.